

# MATERIAL SAFETY DATA SHEET

Pickering Laboratories, Inc • 1280 Space Park Way, Mountain View CA 94043 USA • 650 694 6700 • Fax 650 968 0749

**PRODUCTS:** Regenerant for Polyamines Cation-exchange (K+) Columns  
**Cat. No.** K130

## Section I – General

FORMULA and CAS #: KOH [1310-58-3]; 2-Propanol [67-63-0]  
CHEMICAL NAME: Potassium hydroxide, 0.10N  
SYNONYMS: None  
CHEMICAL FAMILY: Aqueous alkali solution

## Section II – Hazardous Ingredients

1: Potassium hydroxide, 0.10N, pH 13

## Section III – Physical Data

MELTING POINT: Not available  
BOILING POINT: 100°C (approximately)  
VAPOR PRESSURE: < 17 mm Hg @ 20°C  
% VOLATILITY BY VOLUME: 98+%  
APPEARANCE: Clear, odorless solution  
SOLUBILITY: Aqueous solution

## Section IV – Toxicity Data

RTECS #: TT2100000  
RTECS NAME: Potassium hydroxide  
REVIEWS: Only selected Registry of Toxic Effects of Chemical Substances (RTECS) data for crystalline KOH (pure) are presented here; K130 is 0.10N KOH. Refer to actual entry in RTECS for complete information.

## Section V – Health Hazards and First Aid

ACUTE EFFECTS: For crystalline KOH: Orl-rat LD<sub>50</sub>: 365 mg/kg; may be fatal if inhaled, swallowed, or absorbed through skin. Depending on the intensity and duration of exposure, effects may vary from mild irritation to severe destruction of tissue. The K130 solution with a concentration of 0.005N KOH will irritate skin, eyes, mucous membranes, and upper respiratory tract; it can also be corrosive and causes burns.  
CHRONIC EFFECTS: Not established  
EYE CONTACT: Flush with plenty of water for at least 15 minutes; assure adequate flushing by separating eyelids with fingers. Get medical attention.

SKIN CONTACT: Rinse with 1% acetic acid (or vinegar) to neutralize, followed with plenty of water while removing contaminated clothing and shoes. Wash contaminated clothing before reuse. For chemical burns, apply sterile bandage securely, but not too tightly. Get medical attention.

INGESTION: Give water freely and/or 1% acetic acid (or vinegar), followed by milk. Do not induce vomiting. Get medical attention immediately.

### **Section VI – Fire and Explosion Hazards**

FLASHPOINT: Not flammable

EXTINGUISHING MEDIA: Use extinguishing media appropriate to surrounding fire conditions.

FIREFIGHTING PROCEDURE: Wear self-contained breathing apparatus and protective clothing to prevent contact with skin and eyes.

UNUSUAL HAZARDS: Not applicable

EXPLOSIVE PROPERTIES: Not explosive

### **Section VII – Reactivity**

GENERAL: Stable

INCOMPATIBILITIES: Store away from strong acid. Primary and secondary amines will cause non-hazardous contamination of this solution.

HAZARDOUS COMBUSTION OR

DECOMPOSITION PRODUCTS: Will not occur.

### **Section VIII – Spill or Leak Procedures**

SPILL PROCEDURE: Wear eye protection and rubber / latex / vinyl gloves. Neutralize spill with diluted acetic acid. Soak up spill with rags, paper towels, sponge; rinse away or discard. Clean spill-area thoroughly with water.

WASTE DISPOSAL: This solution may be sent to an EPA-approved waste disposal facility. Comply with all federal, state, and local regulations.

### **Section IX – Precautions for Handling and Storage**

SAFETY EQUIPMENT: Chemical safety goggles, laboratory coat, rubber / latex / vinyl gloves, safety-shower with eye-wash.

HANDLING PROCEDURES: Avoid eye and skin contact. Do not ingest. Wear safety glasses and gloves.

STORAGE PROCEDURES: Store away from strong acid, at room temperature.

This information is believed to accurate and represents the best information currently available to us. It is offered only for your consideration, investigation, and verification. Pickering Laboratories disclaims any liability incurred from the use of this product and shall not in any event be liable for any special, incidental, or consequential damages arising from such use. The information provided herein relates only to the specific product designated and may not be valid where such product may be subject to federal, state, or local laws or regulations.